

gMax 2 PRO

Diagram

Power Wire 18/4 SJOOW Portable Cord 300V UL/CSA
<https://www.wireandcableyourway.com/18-4-sjoow-portable-cord-300v-ul-csa>

15x20 Extruder Drag Chain (RobotDigg DC15-20_OPEN)

Extruder Drive Gear (RobotDigg RDGFDB)


U604ZZ 604UU Groove Bearing

Sunon 12V Blower Fan (DigiKey)

Genuine BLTouch Bed Sensor

Hotend Nozzle (E3D v6 Compatible)

3D Printed Fan Shroud
(Found in gMax 3D Printed .stl Files)





Extruder

Hotends

E3D Chimera hotend
E3D 40 Watt 12V heater cartridges
E3D Thermistors

BIQU 2in1 hotend
FYSETC HT-NTC100K thermistor
Triangle labs 50 Watt 12V heater cartridge

Slice engineering copperhead hotend w/ groove mount
Triangle labs 450C T-D500 thermistor
Triangle labs 50 Watt 12V heater cartridge



Other:
SSR Case:
Genuine Fotek Solid State Relay

For illustrative purposes only. gCreate will not be held liable for incorrect installation, purchase or modifications to any parts on the gMax printer